



## **Regular Cover**

2-year limited agaisnt manufacturing defects' Brass grommets with hooks are guaranteed for life.

#### **Industrial Covers**

2-year limited warranty on the 7-ounce fabric and 5-year limited warranty on the 12-ounce fabric against manufacturing defects.\*

\*A manufacturing defect would be apparent during the installation of the shelter. Inspect your shelter after assembly to detect any apparent defects.

# Our fabrics meet the requirements of the BNQ 3910-700 standard (tear resistance, stretch resistance, UV protection, and lamination).

This warranty does not apply to damage caused by excessive snow or ice weight, extreme winds, prolonged sun exposure (summer), abrasion caused by any modification or addition to the structure, friction with the ground, failure to follow Tempo's installation and safety recommendations, negligence, improper storage (the fabric must be dry and clean when stored), or acts of God. Transportation, installation, and dismantling costs are the responsibility of the consumer.

A possible infiltration of water through the seams is not considered a defect. Due to the sewing process, it is impossible to guarantee that there will be no water infiltration through the holes made by the stitching.

### Structure

10-year limited warranty against manufacturing defects.

This warranty does not apply to damage or collapses caused by excessive snow or ice weight, extreme winds, any modification or addition to the structure other than original Tempo parts, failure to follow Tempo's installation and safety recommendations, or acts of God. Transportation, installation, and dismantling costs are the responsibility of the consumer.

After inspection, if Tempo determines there is a manufacturing defect in its product, it will be repaired or replaced at Abris Tempo's sole discretion.

\*Handling fees apply starting from the second year.

## **ATTENTION**

- DANGER DO NOT USE CONCRETE BLOCKS TO ANCHOR THE SHELTER. THIS PRACTICE IS UNSAFE.
- Do not leave the vehicle running inside the shelter.
- To reduce the risk of collapse, do not allow snow and ice to accumulate on the roof; use a snow shovel from outside the shelter and clear both sides alternately; do not clear only one side at a time.
- For your safety, consult one of our experts if you plan to install a shelter in the following administrative regions: Bas-Saint-Laurent; Côte-Nord; Gaspésie-Îles-de-la-Madeleine; Nord-du-Québec.